

Ex. 5 DP / Ex. 7(A)

Ex. 5 DP / Ex. 7(A)

for violations of the Resource Conservation and Recovery Act at its facility located at 930 Port Street, in Easton, Maryland. EPA determined that there were violations of the Underground Storage Tank (“UST”) regulations found at 40 C.F.R. § 280, and the authorized UST regulations of the Maryland Department of the Environment.

Ex. 5 DP / Ex. 7(A)

Ex. 5 DP / Ex. 7(A)